Qtv:

Um:

Each

Date:

Friday, 3/24/2006 8:34:12 AM

User:

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

: D1005

: Z_CUSTOM

: RTN 461

: NA

: NIA IVIA

: 3/31/2006

Customer Job Number

: CC-DAR01 Dart Aerospace Ltd.

: 26375

Estimate Number

: 10804

P.O. Number

AIV:

This Issue Prsht Rev.

Previous Run

: 3/24/2006

First Issue

: NC

: 3/24/2006 : 00015

S.O. No. : NA

Written By Checked & Approved By

Comment

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 QC5 INSPECT WORK TO CURRENT STEP



Comment: INSPECT RTN 461

2.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1:



Comment: SMALL & MEDIUM FAB RESOURCE 1

REMOVE LABELS AND DISCARD/DISASSEMBLE HARDWARE

06:03:27

3.0

5.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

RE-POWDER COAT PER RS1004, QS005 (4.3.5.1)

4.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1 RE-ASSEMBLE PER DRWG D1005 TRACK ANY NEW HARDWARE /B/N'S



		1
		į
÷		
ÁF-		
		Î
	·	1

Date:

Friday, 3/24/2006 8:34:12 AM

User:

Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D1005

Job Number: 26375

Part Number: Z_CUSTOM

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

INSPECT WORK TO CURRENT STEP





Comment: INSPECT WORK TO CURRENT STEP 7.0

QC5


PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

REPACKAGE PER PPP



8.0



Comment: DOCUMENT



Job Completion





- 4

